

(ORIGINAL FOR RECIPIENT)

Sl No.	Description of Goods and Services	HSN/SAC	Quantity	Rate	per	Disc. %	Amount
	Repair of Door Phone CP PLUS, VIDEO DOORPHONE, REPLACEMENT OF SWITCH OF OUTDOOR PANEL	998713					350.00
2	Service Charges WORK DONE AT MANISH SIR HOME	998713					600.00
							950.00
	SGST-9%				9 %		85.50
	CGST-9%				9 %		85.50
	Total						₹ 1,121.00

Indian Rupees One Thousand One Hundred Twenty One Only

Tax Amount (in words) **Indian Rupees One Hundred Seventy One Only**

2017
SOFTLINK SYSTEMS
NEW DELHI
Authorised Signatory

This is a Computer Generated Invoice

FIELD ENGINEER'S SERVICE REPORT

Date 15/10/20

SOFTLINK SYSTEMS




No. 5512



COMPUTER HARDWARE, COMPUTER ACCESSORIES, CCTV CAMERA,
ATTENDANCE MACHINE, EPBAX SYSTEM & NETWORKING SOLUTIONS

C-164, Mayapuri Industrial Area Phase II, 3rd Floor, Near Gulab House / Casa Royal Banquet, New Delhi-110064
Tel.: 011 28126641 M.: 9810634438, 9818534384, E-mail : admin@softlinksystems.co.in • softsys2009@gmail.com

Name of the Customer		Contact Person	Estimate
G. T. Resid.		Mr./Mrs./Ms.	NC
Address		Call No. :	
EC 34 MAYA EN-CLAV		CY	
Item reported		AMC ☐ Paid Call..... Warranty ☐	
Door Bell Broken.		Action	
		Repairing to Door Bell Switching on the door bell OK. The work is done.	
		In Time	Out Time
		12:30 PM	10:45 PM
Further pending action required (If any)		Customer remarks & signature	
None		  Engineer's signature & Name	